



Ministerio de Fomento
Subsecretaría
Dirección General de Aviación Civil

AIRWORTHINESS

DIRECTIVE

NUMBER:
01-04

SHEET:
1 / 1

AFFECTED PRODUCT: Aircraft C-212 -300 and -400 (see EADS-CASA Service Bulletin referenced below for serial number applicability).

MANUFACTURER: EADS-CASA.

ISSUE DATE: March 23rd, 2004.

REFERENCE: EADS-CASA Service Bulletin 212-22-15.

EFFECTIVE: The day after the issue date.

DESCRIPTION: HONEYWELL, has identified a series of own manufactured actuators, P/N 7002260-922 and P/N 7002260-923 installed in autopilot system, SPZ4500, whose failure can take to a potential unsafe flight conditions to the C-212 aircraft, that incorporate as unique system to command, by means of the autopilot, the surfaces of control of ailerons, rudder and elevator. In order to avoid this unsafe condition the installed serial numbers shall be identified and compared with the affected serial numbers and those affected shall be removed and submitted for modification, according to the instructions presented by the EADS-CASA Service Bulletin of the reference.

COMPLIANCE SCHEDULE: The requirements of this Airworthiness Directive shall be complied with before two months after the effectivity date.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil.
To the attention of: J. A.. Basañez.
Paseo de la Castellana, 67. 28071 Madrid
Correo electrónico: jabasanez@mfom.es
Teléfono: +34 91597.8859; +34 91.5978641
Fax: +34 91597.8584

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE

APROBADO POR EASA
CON Nº DE REF. 2004-3342
EN FECHA 30/03/2004