

Ministerio de Obras Públicas y Transportes Dirección General de Aviación Civil

AIRWORTHINESS DIRECTIVE

NUMBER:

02/94

SHEET:

AFFECTED PRODUCT:

CASA CN-235, series aircraft.

MANUFACTURER:

CONSTRUCCIONES AERONAUTICAS S.A. (CASA)

ISSUE DATE:

August, 1994

REFERENCE:

CASA 235-52-23 Service Bulletin, original or

subsequent approved revisions .

EFFECTIVF:

August, 1994

DESCRIPTION:

Due to the possibility of initiation of cracks produced by fatigue in the guide hooks of the ramp door frame, these elements must be replaced by new reinforced ones, in accordance with instructions indicated in the CASA SB 235-52-23 Service Bulletin.

COMPLIANCE SCHEDULE:

The above refered elements should be replaced

before 17000 flights.

ADDITIONAL INFORMATION:

For further information contact with: Dirección General de Aviación Civil

Area Técnica de Certificación

Att. Sr. Iglesias.

Plaza de S. Juan de la Cruz s/n

28071 MADRID Tfn.: 34-1-5976961 Fax.: 34-1-5976853 TX: 48339 CIAL E

AFTN: LEAC ZX C