



Ministerio de Fomento
Secretaría de Estado de
Infraestructuras y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:
02 / 99

SHEET:
1 / 1

AFFECTED PRODUCT: ULM Volero.

MANUFACTURER: Ultraligeros de España.

ISSUE DATE: 21 June, 1999.

REFERENCE: Service Bulletin BS VL-1/98.

EFFECTIVE : Upon reception.

DESCRIPTION: As a result of cracks detected in the rear bar (ref 2080-1) of ULM Volero aircraft, the Dirección General de Aviación Civil issues this Airworthiness Directive to inspect such bar every 50 hours so that at the first sign of fissure, deformation or change in colour of this part, it will proceed to its replacement following instructions from Service Bulletin BS VL-1/98..

COMPLIANCE SCHEDULE: Before the first flight.

ADDITIONAL INFORMATION: For further information contact with:

Dirección General de Aviación Civil.
Subdirección General de Control del Transporte Aéreo.
Area Técnica de Certificación.
Atn. Mr. Fernando García Ocaña
Paseo de la Castellana, 67. 28071 Madrid.

Tel.: +34 91 597 71 44

Fax: +34 91 597 85 84

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE