



Ministerio de
Obras Públicas y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

03/94

SHEET:

AFFECTED PRODUCT: CASA CN-235, series aircraft.

MANUFACTURER: CONSTRUCCIONES AERONAUTICAS S.A. (CASA)

ISSUE DATE: August, 1994

REFERENCE: CASA 235-53-20 Service Bulletin, original or subsequent approved revisions .

EFFECTIVE: August, 1994

DESCRIPTION: Cracks in the fuselage, in the wing to fuselage connection fitting area have been detected in the fatigue test. To preclude the development of cracks, a reinforcement must be installed in the aforementioned zone of fuselage, following the instructions of CASA 235-53-20 Service Bulletin.

COMPLIANCE SCHEDULE: The above referred modification should be accomplished before of 17000 flights.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
Att. Sr. Iglesias.
Plaza de S. Juan de la Cruz s/n
28071 MADRID
Tfn.: 34-1-5976961
Fax.: 34-1-5976853
TX: 48339 CIAL E
AFTN: LEAC ZX C

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.