



Ministerio de Obras Públicas, Transportes
y Medio Ambiente
Secretaría General para los Servicios
de Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

03/96

SHEET:

1/2

- AFFECTED PRODUCT** : All CASA C-212 Aircraft Models.
- MANUFACTURER** : Construcciones Aeronáuticas, S.A.
- ISSUE DATE** : May 13 , 1996.
- REFERENCE** : CASA Service Bulletin 212-57-10,
Original or approved revisions.
- EFFECTIVE DATE** : Upon reception.
- DESCRIPTION** : Due to cracks detected in the inner
flap fittings of some C-212
airplanes, an inspection of those
elements must be performed according
to CASA Service Bulletin 212-57-10
Original or later approved
revisions.
- COMPLIANCE** : The inspection referred above must
be performed no later than 100
flight hours after the effective
date of this A.D.
- If cracks are detected, the
modification described in the
referenced S.B. must be
accomplished.
- If cracks are not detected, and the
modification in the S.B. is not
accomplished, the inspection must be
repeated to intervals not exceeding
100 flight hours.

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.



Ministerio de Obras Públicas, Transportes
y Medio Ambiente
Secretaría General para los Servicios
de Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:
03/96

SHEET:
2/2

ADDITIONAL INFORMATION : For any additional information con-
tact: Dirección General de Aviación
Civil.
Area Técnica de Certificación.
(J. Díaz)
Plaza de San Juan de la Cruz s/n
28071 Madrid
Tlf: 34-1-5976930
Fax: 34-1-5976853
Tlx: 48339 CIAL E
AFTN: LEAC ZX CX.

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.