



Ministerio de
Obras Públicas y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

05/94

SHEET:

AFFECTED PRODUCT: CASA CN-235, series aircraft.

MANUFACTURER: CONSTRUCCIONES AERONAUTICAS S.A. (CASA)

ISSUE DATE: August, 1994

REFERENCE: CASA 235-53-21 Service Bulletin, original or subsequent approved revisions .

EFFECTIVE: August, 1994

DESCRIPTION: As consequence of failure, in the fatigue test, of the longitudinal rod end of wing to fuselage attachment, and to preclude the development of cracks, the replacement of above referred elements must be accomplished according to the instructions of the Service Bulletin CASA 235-53-21.

COMPLIANCE SCHEDULE: These rods ends should be replaced before 16000 flights.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
Att. Sr. Iglesias.
Plaza de S. Juan de la Cruz s/n
28071 MADRID
Tfn.: 34-1-5976961
Fax.: 34-1-5976853
TX: 48339 CIAL E
AFTN: LEAC ZX C

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.