



Ministerio de
Obras Públicas y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER

6/91

SHEET:

1/1

AFFECTED PRODUCT:

CASA Aircraft model C-212-200 equipped with Garrett Engines models:

TPE331-10-501C
TPE331-10-511C
TPE331-10R-501C
TPE331-10R-511C
TPE331-10R-502C
TPE331-10R-512C
TPE331-10R-513C

and model C-212-300 equipped with Garrett Engine model

TPE331-10R-513C

that incorporate in the fuel manifold the assemblies P/N 3102460-1/-2 manufactured by Aeroquip.

MANUFACTURER:

CONSTRUCCIONES AERONAUTICAS., S.A.

ISSUE DATE:

27 September 1991

REFERENCE:

Alert Service Bulletin nº TPE331-A73-0190 issued by Garrett Engine Division dated August 23, 1991, or later revisions F.A.A. approved.

EFFECTIVE:

Upon reception.

DESCRIPTION:

To avoid fuel leaks, due to cracks caused by improper torquing procedures of the assemblies P/N 3102460-1 (AE705912-1) and P/N 3102469-2 (AE705912-2), that could generate an unsafe flight condition, the implementation of the Alert Service Bulletin nº TPE331-A73-0190 from Garrett Engine Division is required.

COMPLIANCE SCHEDULE:

Before next flight.

ADDITIONAL INFORMATION:

For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
(Attn.: Sr. Majado)
Plaza San Juan de la Cruz, s/n.
28071 MADRID Tfn.: 34-1-553.79.76
TX: 48339 CIAL E FAX: 34-1-553.53.14
AFTN: LEAC ZX CX