



Ministerio de Fomento
Secretaría de Estado de Infraestructuras
y Transportes
Dirección General de Aviación Civil

AIRWORTHINESS
DIRECTIVE

NUMBER:
09/96

SHEET:
1/1

AFFECTED PRODUCT: All CASA CN-235 Series.

MANUFACTURER: CONSTRUCCIONES AERONAUTICAS S.A (CASA)

ISSUE DATE: 7 December, 1996.

REFERENCE : Service Bulletin CASA SB 235-24-07,
original issue or further approved
revisions.

EFFECTIVE : 18th December, 1996.

DESCRIPTION: During a CASA flight test and once the
crew intentionally shut an engine down,
it was not possible to restart again by
using of batteries. After landing an
inspection was performed which revealed
the nº 1 bus bar fuse was burned.
To avoid recurrence, the Service
Bulletin 235-24-07 issued by CASA which
install a contactor in the circuit must
be accomplished.

COMPLIANCE SCHEDULE: Within the next six months after the
effective date of this A.D.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
Attn. Sr. Ramirez
Pº de la Castellana, 67
28071 MADRID
Tlf.: 34.1.597-6865
FAX : 34-1-5976853
TLX:48339 CIAL E
AFTN: LEAC ZX CX