



Ministerio de Fomento
Secretaría de Estado de Infraestructuras
y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

10/96

SHEET:

1/2

AFFECTED PRODUCT: All CASA C-212 Aircraft Models.

MANUFACTURER: Construcciones Aeronáuticas, S.A. (CASA).

ISSUE DATE: November 5, 1996.

REFERENCE: CASA Document COM 212-252.

EFFECTIVE DATE: November 15, 1996.

DESCRIPTION: Since electrical spark marks has been detected on several fuel pumps P/N A/M 2C37-2 installed in C-212 airplanes, and in order to avoid possible damages that could affect the airplane integrity, the tasks described in CASA document COM 212-252 must be accomplished.

COMPLIANCE: A visual inspection of the external face of the pump cover plate must be performed, according to the intructions of the referenced document, in a period not exceeding 100 flight hours, from the effective date of this A.D. The above inspection must be repeated to intervals not exceeding 300 flight hours, just in case that tasks in paragraphs 4,5,6 and 7 of the referenced document have not been carried out.



Ministerio de Fomento
Secretaría de Estado de Infraestructuras
y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

10/96

SHEET:

2/2

ADDITIONAL INFORMATION : For any additional information contact:
Dirección General de Aviación Civil.
Area Técnica de Certificación.
(J. Díaz.)
Plaza de San Juan de la Cruz s/n
28071 Madrid
Tlf: 34-1-597-6930
Fax: 34-1-597-6853
Tlx: 48339 CIAL E
AFTN: LEAC ZX CX.

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE