



Ministerio de
Obras Públicas y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER

01/92

SHEET:

1/1

AFFECTED PRODUCT: Aircraft CASA CN-235, CN-235-100 and CN-235-200.

MANUFACTURER: CONSTRUCCIONES AERONAUTICAS S.A. (CASA)

ISSUE DATE: January, 14 1992

REFERENCE: Document CASA Maintenance Instruction COM 235-58 dated November 21, 1991 or subsequent revisions.

EFFECTIVE: January, 14 1992

DESCRIPTION: Due to the possibility of initiation of cracks produced by corrosion in the support lug of the Flap track, must be accomplished the usual inspection show in the Maintenance Instruction CASA COM 235-58.

Any alternate mean of compliance which provides an acceptable level of safety, may be used, subject to previous approval by DGAC.

COMPLIANCE SCHEDULE: The inspection established in this Airworthiness Directive, must be accomplished at the following intervals:

a) Aircraft with less than 2000 flight hours:

1) First Inspection: During the next "C" or anual inspection.

2) Interval: Each "Y" inspection.

b) Aircraft with more than 2000 flight hours:

1) First Inspection: Before of the first fly.

2) Interval: Each "Y" inspection.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
Attn. Sr. Iglesias.
Plaza de S. Juan de la Cruz s/n.
28071 MADRID
Tfn.: 34-1-533.79.76 TX: 48309 CIAL E
FAX: 34-1-553.50.14 AFTN: LEAC TX CX

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.