



MINISTERIO DE TRANSPORTES,
TURISMO Y COMUNICACIONES
DIRECCION GENERAL DE AVIACION CIVIL

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

02/91

SHEET:

1/1

AFFECTED PRODUCT: Fluorescent lighting lamp connectors 3185-1A and Remote Power Units (RPU), P/Ns. TR992, TR992-A, TR992-1, TR992-3, TR992-4 and TR992-5 manufactured by S.E.L.A, Laboratoire Abadie installed in CASA model CN235. Series

MANUFACTURER: S.E.L.A. Laboratoire Abadie.

ISSUE DATE: January , 1.991

REFERENCE: Airworthiness Directive FAA-AD-90-07-08.

EFFECTIVITY DATE: January 26 , 1.991

DESCRIPTION: To prevent smoke, fire and possible electrical shock, or electromagnetic interference to flight critical or essential systems produced by the affected product, accomplish the modification for installation of connectors and RPU above noted. Until this modification is introduced, should be accomplished the inspections noted in the referenced Directive.

COMPLIANCE: This compliance will be performed according to instructions indicated in Airworthiness Directive FAA-AD-90-07-08.

COMPLIANCE TIME: January 31, 1.991.

ADDITIONAL INFORMATION: Dirección General de Aviación Civil
Area Técnica de Certificación
Attn. Sr. Iglesias
Pza. San Juan de la Cruz, s/n.
28071 MADRID

Tlfn. 91-533.79.76

FAX: 91-553.50.14

Tx.: 48339 CIAL E

AFTN: LEAC ZX CX

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.