



Ministerio de
Obras Públicas y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER

02/92

SHEET:

1/1

AFFECTED PRODUCT: CASA Aircraft model C-212-200 equipped with Garrett Engines models:

TPE331-10-501C
TPE331-10-511C
TPE331-10R-501C
TPE331-10R-511C
TPE331-10R-502C
TPE331-10R-512C
TPE331-10R-513C

and model C-212-300 equipped with Garrett Engine model: TPE331-10R-513C, that incorporate in the fuel manifold the assemblies P/N 3102460-2 manufactured by Stratoflex

MANUFACTURER: CONSTRUCCIONES AERONAUTICAS S.A.

ISSUE DATE: 23 January 1992

REFERENCE: Airworthiness Directive FAA-AD-92-02-19 and Alert Service Bulletin n° TPE331-A73-0198 revision 1, issued by Garrett.

EFFECTIVE: Upon reception.

DESCRIPTION: To avoid fuel leaks, that could generate an unsafe flight condition, caused by cracks detected in fuel hose P/N 3102469-2 manufactured by Stratoflex during a time period, the implementation of the Alert Service Bulletin n° TPE331-A73-0198 from Garrett Engine Division is required.

COMPLIANCE SCHEDULE Before next flight.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
(Attn. Sr. Iglesias)
Plaza de S. Juan de la Cruz s/n.
28071 MADRID
Tfn.: 34-1-533.79.76 TX: 48539 CIAL F
FAX: 34-1-553.50.14 APTN: LEAC EX CY

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.