



Ministerio de Obras Públicas, Transportes  
y Medio Ambiente  
Secretaría General para los Servicios  
de Transportes  
Dirección General de Aviación Civil

**AIRWORTHINESS  
DIRECTIVE**

NUMBER:  
02/96

SHEET:  
1/2

**AFFECTED PRODUCT:** All CASA C-212 Aircraft Models.

**MANUFACTURER:** Construcciones Aeronáuticas, S.A. (CASA).

**ISSUE DATE:** May /3 , 1996.

**REFERENCE:** CASA Document COM 212-224.

**EFFECTIVE DATE:** Upon reception.

**DESCRIPTION:** In at least one C-212 airplane, cracks have been detected in the structural elements defined in referenced document, located on the false spar of the wing. Based on that, an inspection must be performed in the rest of the fleet, according to CASA document COM 212-224, to determine the existence of actual cracks, carrying out the repair and/or modification of the affected elements.

**COMPLIANCE:** A detailed visual inspection of the area must be performed in a period, not exceeding 1.200 flight hours, from the effective date of this A.D.

In case that cracks are determined to exist proceed to repair and/or to modify the structural elements according to approved instructions.

In case that cracks are not determined to exist, the inspection must be repeated each 1.200 flight hours.

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.



Ministerio de Obras Públicas, Transportes  
y Medio Ambiente  
Secretaría General para los Servicios  
de Transportes  
Dirección General de Aviación Civil

**AIRWORTHINESS  
DIRECTIVE**

NUMBER:  
02/96

SHEET:  
2/2

ADDITIONAL INFORMATION : For any additional information contact:  
Dirección General de Aviación Civil.  
Area Técnica de Certificación.  
(J. Díaz.)  
Plaza de San Juan de la Cruz s/n  
28071 Madrid  
Tlf: 34-1-597-6930  
Fax: 34-1-597-6853  
Tlx: 48339 CIAL E  
AFTN: LEAC ZX CX.

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.