



Ministerio de Fomento
Secretaría de Estado de
Infraestructuras y Transportes
Dirección General de Aviación Civil

AIRWORTHINESS

DIRECTIVE

NUMBER:
03 / 99

SHEET:
1 / 1

AFFECTED PRODUCT: ULTRAMAGIC Balloons equipped with tanks Model M-20 with S/N from 236 to 262 and Model M-30 with S/N from 334 to 415, fitted with Fisher connection.

MANUFACTURER: ULTAMAGIC S.A.

ISSUE DATE: 14 October 1999.

REFERENCE: Service Bulletin 1/994 issued by ULTRAMAGIC or later approved revisions.

EFFECTIVE : On reception.

DESCRIPTION: Since It has been verified that under some circumstances, the inner part of connector Fisher M220M can disassemble by itself, and that these parts (ring, spring, etc) can fall into the cylinder or block the 1/4 main valve, the Fisher M220M connector must be replaced by Rego 7141M connector, in accordance with the Ultramagic Service Bulletin mentioned under "Reference" above.

COMPLIANCE SCHEDULE: Before any manipulation of the tank, except for the replacement of the connector.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil.
Subdirección General de Control del Transporte Aéreo.
Delegación de Seguridad en Vuelo nº 4
Attn. Mr. F Piera.
Aeropuerto de Sabadell – Barcelona - SPAIN
e-mail: fpiera@mfom.es
Tel.: +34 93.711.7661
Fax: +34 93 711.2030

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE