



Ministerio de Obras Pùblicas, Transportes
y Medio Ambiente
Secretaría General para los Servicios
de Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:
04/96

SHEET:
1/1

AFFECTED PRODUCT : All CASA C-212 Aircraft Models.

MANUFACTURER : Construcciones Aeronáuticas, S.A.

ISSUE DATE : May 13 , 1996.

REFERENCE : Service Bulletin CASA 212-76-08,
original or later approved
revisions.

EFFECTIVE DATE : Upon reception.

DESCRIPTION : In order to determine the condition
of the control levers slot
protections installed in the
pedestal according to the CASA
Service Bulletin nº 212-76-05, a
visual inspection of those items
must be performed. If deterioration
is determined to exist, the CASA
Service Bulletin nº 212-76-08,
original or later approved revision,
must be accomplished.

COMPLIANCE : 300 flight hours or 3 months
whichever occurs first from the
effective date of this Directive.
The inspection must be repeated to
intervals not exceeding the above
period until S.B. 212-76-08 is
accomplished.

ADDITIONAL INFORMATION : For any additional information con-
tact:
Dirección General de Aviación Civil.
Area Técnica de Certificación.
(J. Díaz)
Plaza de San Juan de la Cruz s/n
28071 Madrid
Tlf: 34-1-597-6930
Fax: 34-1-597-6853
Tlx: 48339 CIAL E
AFTN: LEAC ZX CX.

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.