



AFFECTED PRODUCT: All Model C-212 Series airplanes.

REFERENCE: C.A.S.A. Service Bulletin S/B 212-31-12 R 1,
dated January 18, 1988.

DESCRIPTION:

A. Prior to April 15, 1988, install an artificial stall warning system in accordance with CASA Service Bulletin aboved refered.

B. An alternate means of compliance or adjustment of the compliance time, which provides an acceptable level of Safety must be approved by this DGAC.

C. This Directive becomes affective: February 15,1.988

FOR FURTHER INFORMATION CONTACT: Servicio de Material del Transporte Aéreo(Airworthiness) Subdirección General del Control del Transporte Aéreo, Dirección General de Aviación Civil. Mailing address: C/Agustín de Bethencourt, 25. 28071 MADRID-SPAIN. Phone (34-1) 2349059. Tx.48339 CIAL E. Fax. (34-1)2345016. APTN. LEAC ZX ED