



MINISTERIO DE TRANSPORTES,
TURISMO Y COMUNICACIONES
DIRECCION GENERAL DE AVIACION CIVIL

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

03-89

SHEET:

1 of 2

AFFECTED PRODUCT : Aircraft C.A.S.A. Model CN-235, serial numbers :

C-001, C-006

C-007, C-010

MANUFACTURER : Construcciones Aeronauticas, S.A. (C.A.S.A.)

ISSUE DATE : June, 9 1.989.

REFERENCE : C.A.S.A. Service Bulletin No 235-53-01, dated June 1, 1989, or later D.G.A.C. approved revisions

EFFECTIVITY: June, 9 1.989

DESCRIPTION : To ensure structural integrity of the windshield , its structure must be modified according to Service Bulletin of C.A.S.A Nr. 235-53-01, dated June, 1 of 1989, or later D.G.A.C. approved revisions.

COMPLIANCE TIME : Before the aircraft affected reach their first 1000 pressurized flight cycles.

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.



MINISTERIO DE TRANSPORTES,
TURISMO Y COMUNICACIONES
DIRECCION GENERAL DE AVIACION CIVIL

**AIRWORTHINESS
DIRECTIVE**

NUMBER.

03-89

SHEET:

2 of 2

ADDITIONAL INFORMATION : For any additional information
contact with :

Dirección General de Aviación Civil
Servicio de Material (Mr. Ramirez)
C/ Agustin de Betancourt, 25
28071 MADRID

TLF. 34-1-2349059 TLX: 48339 CIAL E

FAX: 34-1-5352692 AFTN: LEAD ZX CM

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.