



MINISTERIO DE TRANSPORTES,
TURISMO Y COMUNICACIONES
DIRECCION GENERAL DE AVIACION CIVIL

**AIRWORTHINESS
DIRECTIVE**

NUMBER

03/91

SHEET:

1/1

AFFECTED PRODUCT: Aircraft CASA CN-235-100, with serial numbers: C-018; C-029; C-030; C-032; C-033.

MANUFACTURER: CONSTRUCCIONES AERONAUTICAS S.A. (CASA)

ISSUE DATE: April 11, 1991

REFERENCE: CASA Service Bulletin n° 235-33-07 dated March 8, 1991 or subsequent approved revisions.

EFFECTIVE: April 15 1991

DESCRIPTION: To provide cabin attendant with easy access to the emergency lighting system switch, a relocation of this switch must be performed following the procedures established in CASA SB 235-33-07, or subsequent revisions issued by CASA and approved by DGAC.

An alternate means of compliance which provides an acceptable level of safety, may be used subject to previous approval by DGAC.

COMPLIANCE SCHEDULE This airworthiness directive shall be accomplished before the 31th may of 1991.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
Attn. Sr. Garvía
Plaza de S. Juan de la Cruz s/l.
28071 MADRID
Tfn.: 34-1-533.79.76 TX: 49339 CIAL E
FAX: 34-1-533.50.14 AFTN: LEAC ZX CX

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.