



MINISTERIO DE TRANSPORTES,
TURISMO Y COMUNICACIONES
DIRECCION GENERAL DE AVIACION CIVIL

AIRWORTHINESS
DIRECTIVE

NUMBER

04/91

SHEET:

1/1

AFFECTED PRODUCT: Aircraft CASA CN-235-100, with serial numbers:
C-018; C-029; C-030; C-032; C-033.

MANUFACTURER: CONSTRUCCIONES AERONAUTICAS S.A. (CASA)

ISSUE DATE: April 11, 1991

REFERENCE: CASA Service Bulletin n° 235-33-07 dated March
8, 1991 or subsequent approved revisions.

EFFECTIVE: April 15 1991

DESCRIPTION: To prevent the potential risk of damage to the
passenger in the right seat of the forward
right side row (considering flight direction)
due to impact with a structural element from
the cabin right forward door, the suitable
protection, by cushioning of the mentioned
element, must be provided, in accordance with
CASA SE 235-25-14.

An alternate means of compliance which provides
an acceptable level of safety, may be used
subject to previous approval by DGAC).

COMPLIANCE SCHEDULE: This airworthiness directive shall be
accomplished before the 31th May of 1991.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
Attn. Sr. Garvía
Plaza de S. Juan de la Cruz s/n.
28071 MADRID
Tfn.: 34-1-533.79.75 TX: 46999 CIAL E
FAX: 34-1-552.50.14 AFTN: LEAC TX CX

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.