



Ministerio de
Obras Públicas y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

06/94

SHEET:

AFFECTED PRODUCT : CASA CN-235, series Aircraft.

MANUFACTURER : CONSTRUCCIONES AERONAUTICAS S.A
(CASA)

ISSUE DATE : August, 1994.

REFERENCE : CASA nº 235-27-05 Service Bulletin,
original or later approved
revisions.

EFFECTIVE : August, 1994.

DESCRIPTION : Due to the possibility of cracks
initiation produced by
stresscorrosion in the torsion tubes
of the elevator and rudder, these
items shall be inspected or replace,
following the instructions of CASA
Service Bulletin 235-27-05.

COMPLIANCE SCHEDULE: The inspections must be accomplished
in accordance with the intervals
mentioned in the Service Bulletin
235-27-05.

ADDITIONAL INFORMATION : For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
Attn. Sr. Iglesias
Plaza de S. Juan de la Cruz s/n
28071 MADRID
Tfn:34-1-5976961
TX:48339 CIAL E
FAX : 34-1-5976853 AFTN: LEAC ZX CX

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.