



Ministerio de Obras Públicas, Transportes
y Medio Ambiente
Secretaría General para los Servicios
de Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:
06/96

SHEET:
1/1

AFFECTED PRODUCT : All CASA C-212 Aircraft Models.
MANUFACTURER : Construcciones Aeronáuticas, S.A.
ISSUE DATE : May 21, 1996.
REFERENCE : CASA Service Bulletin 212-27-34,
Original or approved revisions.
EFFECTIVE DATE : Upon reception.
DESCRIPTION : Due to corrosion has been detected
in the rudder torsion tube of C-212
airplanes, the modification
described in CASA Service Bulletin
212-27-34 Original or later approved
revisions must be accomplished.
COMPLIANCE : The modification referred above must
be accomplished in a interval no
greater than two months from the
effective date of this A.D.
ADDITIONAL INFORMATION : For any additional information con-
tact: Dirección General de Aviación
Civil.
Area Técnica de Certificación.
(J. Díaz)
Plaza de San Juan de la Cruz s/n
28071 Madrid
Tlf: (34 1)-597-6930
Fax: (34 1)-597-6853
Tlx: 48339 CIAL E
AFTN: LEAC ZX CX.

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.