



Ministerio de Fomento
Secretaría de Estado de Infraestructuras
y Transportes
Dirección General de Aviación Civil

**AIRWORTHINESS
DIRECTIVE**

NUMBER:

08/96

SHEET:

1/1

AFFECTED PRODUCT: All CASA CN-235, Aircraft models.

MANUFACTURER: CONSTRUCCIONES AERONAUTICAS S.A (CASA)

ISSUE DATE: 9 December, 1996.

REFERENCE : Service Bulletin CASA SB 235-55-04.

EFFECTIVE : 18th December, 1996.

DESCRIPTION: To avoid risk of exceeding structural limits of the fin the installation of a structural reinforcement in the fin according with the Service Bulletin cited under "Reference" must be accomplished.

COMPLIANCE SCHEDULE: Within the next six months after the effective date of this A.D.

ADDITIONAL INFORMATION: For further information contact:
Dirección General de Aviación Civil
Area Técnica de Certificación
Attn. Sr. Ramirez
Pº de la Castellana, 67
28071 MADRID
Tlf.: 34.1.597-6865
FAX : 34-1-5976853
TLX:48339 CIAL E
AFTN: LEAC ZX CX

THIS AIRWORTHINESS DIRECTIVE IS A TRANSLATION FROM THE SPANISH ORIGINAL ISSUE.